

KIA Picanto

General Information	
Seller Name	Kyaw Htin Lin
Engine Capacity	1248 CC
Mileage	71124 KM
Fuel Type	Petrol
Transmission Type	Auto
Color	White
Location	Mandalay
Engine condition	77%
Interior and electronics	80%
Exterior condition	78%
Frame and suspension	89%
Total score	81%

Electronics		
Malfunction indication is not present	3	0
Engine DTC check	3	0
ABS system	3	0
Body electricals	3	0
Airbags	4	0
Seat belts	4	0
Guages are working	4	0

Engine/Transmission	Ok/Not Ok	Remarks
V-belt	3	0
Engine oil condition	3	0
Engine oil leaks	3	0
Transmission oil condition	2	0
Transmission oil leakage	3	0
Coolant expansion tank	3	0
Coolant pipes	3	0
Battery voltage	3	0
Radiator condition	3	0
AC condensor condition	3	0
Starter operation	3	0
Engine noise	3	0
Engine vibration	3	0
Radiator fan operation	3	0
Engine mounts	4	0
Exhaust sound	4	0
<b>Interior and Electronics</b>		
<b>Steering Controls</b>		
Lights Lever/Switch is working	3	0
Washer Lever/Switch is working	3	0
Windscreen Wiper	3	0
Horn is working	2	0
<b>Mirrors</b>		
Side Mirror Right is working	3	0
Side Mirror Left is working	3	0

<b>Power/Manual Windows &amp; Central Locking</b>		
Power Window/Manual Lever Right Front is Working	3	0
Power Window/Manual Lever Right Rear is Working	3	0
Power Window/Manual Lever Left Front is Working	3	0
Power Window/Manual Lever Left Rear is Working	3	0
Central Lock System is working	4	0
Remote Lock is working	4	0
<b>Dash/Roof Controls</b>		
Interior Lightings are Working	3	0
Dash Controls - A/C are Working	3	0
Dash Controls - Hazzard Lights are Working	3	0
Audio/Video is Working	3	0
Rear View Camera is Working	3	0
Cigarette Lighter is Working	3	0
Fuel Cap Release Lever/Button is Working	3	0
Bonnet Release Lever/Button is Working	3	0

<b>Interior</b>		
Ceiling is Clean	4	0
Floor is Clean	3	0
Doors Panel is Clean	3	0
Dashboard Condiiton is Clean	3	0
Sunshades are Working	3	0
Driver Seat is Clean	3	0
Passenger Seat is Clean	4	0
Rear Seat is Clean	4	0
Boot Carpet / Mat is Clean	2	0
Boot Board is Clean		

<b>Equipment</b>		
Spare Tire is present	3	0
Tools or Jack is present	3	0

Exterior		
<b>Doors/Windows</b>		
Trunk Lock is Ok	1	0
Door Fittings Front Right	3	0
Door Fittings Rear Right	3	0
Door Fittings Front Left	3	0
Door Fittings Rear Left	3	0
Door Levers Front Right	3	0
Door Levers Rear Right	3	0
Door Levers Front Left	3	0
Door Levers Rear Left	3	0
Front Windshield	3	0
Rear Windshield	3	0
Front Right Door Window	3	0
Rear Right Door Window	3	0
Front Left Door Window	3	0
Rear Left Door Window	3	0


Tyres		
Brand Name	Good Year	
Tyre Size	165/80 R13	0
Front Right	8	100% Remaining Of Tyre Life
Front Left	8	100% Remaining Of Tyre Life
Rear Right	8	100% Remaining Of Tyre Life
Rear Left	8	100% Remaining Of Tyre Life
Spare Tyre	3	0
Rims	3	0

<b>Exterior Lights</b>		
Headlight Right Condition	4	0
Headlight Right is Working	4	0
Headlight Left Condition	4	0
Headlight Left is Working	4	0
Taillight Right Condition	4	0
Taillight Right is Working	4	0
Taillight Left Condition	4	0
Taillight Left is Working	4	0
Number Plate Lights	3	0
Number Plate Lights is Working	3	0
Reverse Light	4	0
Reverse Light is Working	3	0
Fog Lights	4	0
Fog Lights are Working	4	0
<b>Undercarriage</b>		
<b>Steering and and suspension</b>		
Front right tie-rod	2	0
Front left tie-rod	2	0
Front right ball joint	4	0
Front left ball joint	4	0
Front right links	4	0
Front left links	3	0
Front right arm bush	4	0
Front left arm bush	3	0
Front right struts	4	0
Front left struts	3	0
Rear right struts	4	0
Rear left struts	4	0
Rear righ arm bush	4	0
Rear left arm bush	4	0
Right Drive Shaft	3	0
Left Drive Shaft	3	0

<b>Braking system</b>		
Front right brake pads	4	0
Front left brake pads	3	0
Front right brake disk	4	0
Front left brake disk	3	0
Parking brake	4	0
Brake fluid	3	0
<b>Under Body Shields</b>		
Under Body Shields	4	0
Fender Shields	3	0

<b>Body frame check</b>		
radiator support	3	0
Front left Frame	3	0
Front Right Frame	4	
Right Strut tower	4	
Left strut tower	4	
Front subframe	4	0
Firewall	4	0
Rear Boot lock pannel	4	0
Rear boot floor	2	0
Right A pillar	4	0
Left A pillar	4	0
Right B pillar	4	0
Left B pillar	4	0
Right C pillar	3	0
Left C pillar	4	0
Right D pillar	4	0
Left D pillar	4	0

## Exterior Condition



### Legend

**A1:** Small Scratch

**A2:** Scratch

**A3:** Big Scratch

**B:** Dent with scratch

**E1:** Few Dimples

**E2:** Several Dimples

**E3:** Many Dimples

**U1:** Small Dent

**U2:** Dent

**U3:** Big Dent

**R1:** small rust

**R2:** rust

**R3:** severe rust

**W1:** Repair Mark/Wave(hardly detectable)

**W2:** Repair Mark/Wave

**W3:** Obvious Repair Mark/Wave(need to be repainted)

Remarks

ရှေ့ဘယ်ဘက်နှင့် နောက်ညာဘက် အပွန်းအစင်းကြီးရှိ။

Disclaimer: This report is based on the condition of the vehicle on the date

Inspection By

*Kyaw Htin Lin And Ye Naing*



[www.carsdb.com](http://www.carsdb.com)